

**GREGORY S. BELL** Lieutenant Governor

## State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

## **Minerals Inspection Report**

| Rep  | ort Date: 04/06/201          | 5                   |                      | ,            |
|--|------------------------------|---------------------|----------------------|--------------|
| Mine Name: Champlin #1   | Permit Number:               | S/023/0104          | Mine Status:         | Suspended    |
| Operator Name: Nephi Sandstone Corporation   | Inspection Date:             | 04/03/2015          | Permit Fees:         | Delinquent   |
| Inspector(s): Wayne Western  | Inspection Time:             | 2:30 - 2:40 pm      | Bond Amount:         | \$19,700     |
| Attendee(s): none  | Weather:                     | clear and mild      | Bond Escalation:     | 02/10/2014   |
| Inspection Purpose:  |                              |                     | Prior Inspection:    | 11/19/2014   |
| Conclusions and Recommendations On March 25, 2009, the BLM issued a noncompliance of the Division issued MC-2014-42-05 cessation order for 2009-2013, No permit fee or annual report were submit Division issued an FTACO. | failure to maintain adequate | bond, pay permit fe | es and submit annual | reports from |

|                        |   | 1                     |             |
|------------------------|---|-----------------------|-------------|
| Elements of Inspection |   | Evaluated & Commented | Enforcement |
| 1.                     | Permits, Revisions, Transfer, Bonds   | $\boxtimes$           |             |
|                        | Operator has failed to escalated bond or pay permit fees.                                       |                       |             |
| 2.                     | Public Safety (shafts, adits, trash, signs, highwalls)  |                       |             |
|                        | There are highwalls on the site that are stepper than 45 degrees.                               |                       |             |
| 3.                     | Protection of Drainages/Erosion Control   |                       |             |
| 4.                     | Deleterious Material  | $\boxtimes$           |             |
|                        | There is an excavator on site that has been there for several years. There is the potential for | fluid leaks.          |             |
| 5.                     | Roads (maintenance, surfacing, dust control, safety)  |                       |             |
| 6.                     | Reclamation   |                       |             |
| 7.                     | Backfilling/Grading (trenches, pits, roads, highwalls, shafts)                                  |                       |             |
| 8.                     | Soils   |                       |             |
| 9.                     | Revegetation  |                       | H           |
| 10.                    | Other   | П                     | Ä           |

| Inspector's Signature: |  |
|------------------------|--|
| CC: jmccarth@blm.gov   |  |

 $File: \ /C/Users/WAYNEW\sim 1/App Data/Local/Temp/acrord 32\_sbx/A9RCA 92.tmp$ 



Mine: S/023/0104 Page 2 of 2

Inspected: 04/03/2015



Excavator that has been on the site for years.



Stockpile of crushed material on site.



Tire tracks for a large vehicle were on site. The Division cannot tell is there were unauthorized mining activities being conducted.



Steep un-reclaimed highwalls.

